

Airds Moss

Site Name	Plot Label/ Area	Date & time	Plot Name	10-fig Grid Ref	Bearing	2014/ 15 Reference	2014/15 description	2021 Ref.	2021 description/ notes
Airds Moss	A		Phase 1	NS6350226441	120	FP1	General view up slope from north-west corner of survey plot.		
Airds Moss	A		Phase 1	NS6351826431	210	FP2	Grip monitoring quadrat 1. Taken from dam with marker stake, looking up-slope.		
Airds Moss	A		Phase 1	NS6351826431	360	FP3	Grip monitoring quadrat 1. View from southern dam, northwards down grip.		
Airds Moss	A		Phase 1	NS6353626419	200	FP4	Grip monitoring quadrat 2. Taken from dam with marker stake, looking up-slope.		
Airds Moss	A		Phase 1	NS6353626419	360	FP5	Grip monitoring quadrat 2. View from southern dam, northwards down grip.		
Airds Moss	A		Phase 1	NS6356926394	230	FP6	Grip monitoring quadrat 3. Taken from dam with marker stake, looking up-slope.		
Airds Moss	A		Phase 1	NS6356926394	360	FP7	Grip monitoring quadrat 3. View from southern dam, northwards down grip.		
Airds Moss	A		Phase 1	NS6356926394	180	FP8	Grip monitoring quadrat 3. Close up view of pool between grip blocks. Taken from dam adjacent to the marker stake, looking upslope.		
Airds Moss	B		Phase 3	NS6372826481	105	FP1	View from NW corner of sample plot. Prominent hill in centre of shot.		
Airds Moss	B		Phase 3	NS6375526333	48	FP2	View from SW corner of sample plot. Prominent hill left of centre.		
Airds Moss	B		Phase 3	NS6375326334	170	FP3	Grip monitoring quadrat 1. Taken from dam with marker stake, looking up-slope.		

Airds Moss	B		Phase 3	NS6375426329	350	FP4	Grip monitoring quadrat 1. View from southern dam, northwards down grip. Flag in photo indicates marker stake location.		
Airds Moss	B		Phase 3	NS6377426380	170	FP5	Grip monitoring quadrat 2. Taken from dam with marker stake, looking up-slope.		
Airds Moss	B		Phase 3	NS6377226373	2	FP6	Grip monitoring quadrat 2. View from southern dam, northwards down grip. Flag in photo indicates marker stake location.		
Airds Moss	B		Phase 3	NS6378726448	170	FP7	Grip monitoring quadrat 3. Taken from dam with marker stake, looking up-slope.		
Airds Moss	B		Phase 3	NS6378426441	18	FP8	Grip monitoring quadrat 3. View from southern dam, northwards down grip. Flag in photo indicates marker stake location.		
Airds Moss	C		Phase 4	NS6413226102	180	FP1	View from NE corner of plot. Taken from edge of blocked natural drain. Monument in left of frame, view towards slag heaps across Muirkirk Rd.		
Airds Moss	C		Phase 4	NS6408326085	120	FP2	View from NW corner of plot. Monument in centre of frame.		
Airds Moss	C		Phase 4	NS6412426066	105	FP3	Grip monitoring quadrat 1. View of pool behind grip block, taken from the dam with marker stake.		
Airds Moss	C		Phase 4	NS6412426066	33	FP4	Grip monitoring quadrat 1. Taken from dam opposite the marker stake, down the line of the grip.		
Airds Moss	C		Phase 4	NS6414426023	320	FP5	Grip monitoring quadrat 2. View of pool behind grip block, taken from the dam with marker stake.		
Airds Moss	C		Phase 4	NS6414426023	135	FP6	Grip monitoring quadrat 2. Taken from dam opposite the marker stake, down the line of the grip.		

Airds Moss	C		Phase 4	NS6414925969	250	FP7	Grip monitoring quadrat 3. View of pool behind grip block, taken from the dam with marker stake.		
Airds Moss	C		Phase 4	NS6414925969	38	FP8	Grip monitoring quadrat 3. Taken from dam opposite marker stake, down the line of the grip.		
Airds Moss	D		Reference area			N/A	N/A	Airds_D_FP 1	
Airds Moss	D		Reference area			N/A	N/A	Airds_D_FP 2	
Airds Moss	D		Reference area			N/A	N/A	Airds_D_FP 3	
Airds Moss	D		Reference area			N/A	N/A	Airds_D_FP 4	
Airds Moss	D		Reference area			N/A	N/A	Airds_D_FP 5	
Airds Moss	D		Reference area			N/A	N/A	Airds_D_FP 6	
Airds Moss	D		Reference area			N/A	N/A	Airds_D_FP 7	
Airds Moss	D		Reference area			N/A	N/A	Airds_D_FP 8	